

IBM 17 MT 1164

ACCOUNTING MACHINE CONTROL PANEL, TYPES 402-403

CAPD "A" Runs 112-11, 112-12, 112-13, 112-14

3075 FORM 31-9317-8 PRINTED IN U. S. A.




FIGURE 45.—Illustrative example of wiring diagram, type 402-403, control panel.